ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0603	NA	Dasarahalli
Segment No.	**Total Length (m)**	
6/S-W0603/S054444	109.44	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	109.44	77.611773	13.057743	77.611746	13.058731	Dasarahalli main road	Dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains of Ambedkar colony cross road Dasarahalli in ward no. 06 Byatarayanapura sub division	3000000	2015-16
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	RCC drain
Tender	**Work Details**	**Job No. / Work Code**
Tender	RCC drain	006-15-000027
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/17/2016-17	30/04/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/10/2018	27/10/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
V. Chandrappa		0.00
Phone No.	**E-Mail ID**	
9448447181		

Field Inspection Details

Number of Trees

0

Any Other Information

Name

daramsingh

Date of Inspection

13/11/2018

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark